

INDIAN SERVICE

A subsidiary brand platform of Indian Service.

Rate Card of AC Service, Repair & Installation

Call- 9836923786 / 9903703786 / WP- 9836923786

Minimum side Visiting / Inspection Charges Rs. 250/- Adjustable

Maximum Labour Charges per AC Rs. 699/-

Services	
Description	Rate
Split AC Installation	Rs. 1599/-
Vacuuming	Rs. 499/-
Window AC Installation	Rs. 799/-
Extra Civil Work (Santraz) Per Day	Rs. 699/-
Window AC Dismantling	Rs. 499/-
Split AC Dismantling	Rs. 699/-
Indoor Unit Installation	Rs. 699/-
Outdoor Unit Installation	Rs. 799/-
Copper Pipe (Per Ft)	Rs. 320/-
Stand/Angel	Rs. 899/-
Indoor Unit Base Plate	Rs. 799/-
Soft Water Pipe (Per Ft)	Rs. 30/-
Fastener Complete Set	Rs. 250/-
Universal Back Plate	Rs. 550/-
IDU To ODU Wire (Per Ft)	Rs. 45/-
Rapping Tap (10 Ft)	Rs 299/-

Services

Description	Rate
Normal Filter Service Split Window	Rs. 300/-
Split Window AC Jet Pump from Service	Rs. 599/-
Chemical Wash / Service Pump Down Service (Chemical Wash, Re-Install, Gas Charges)	Rs. 1200/- 4400/- 300/-
Full Gas Charging (R-22)	Rs. 2499/-
Gas Top UP (R-22)	Rs. 1200/-
Full Gas Charging (R-32 / R-410)	Rs. 2699/-
1.0-ton Copper Condenser Coil	Rs. 4000/-
1.5,2.0-ton Copper Condenser Coil	Rs. 6000/-
Copper Coil Repair / Welding	Rs. 450/-
Cooling Coil	Rs. As per Service Center
Compressor 1.0 ton (non-Inv)	Rs. As per Service Center
Compressor 1.5 ton (non-Inv)	Rs. As per Service Center
Compressor 2.0 ton (non-Inv)	Rs. As per Service Center
Capillary & Stener	Rs. 750/-
Valve Replace	Rs. 1450/-
Rubber Pad 1 pc	Rs. 60/-
Dead nut 1 pc	Rs. 70/-
Window AC Pin Valve	Rs. 225/-
Flair Nut	Rs. 250/-

Parts

Description	Parts	Labour
Tighten/Replace Thimble	Rs. 399/-	Rs. 325/-
Compressor Connector wires	Rs. 425/-	Rs. 325/-
Adjust Grill Lock	Rs. 350/-	Rs. 60/-
Water Leakage Repair	Rs.	Rs. 599/-
New ODU Fan Motor (Non-Inv)	Rs. 2850/-	Rs. 425/-
ODU Fan Motor Repair (Non-Inv)	Rs. 1800/-	Rs. 425/-
Blower Motor (New)	Rs. 2400/-	Rs. 425/-
Blower	Rs. 1650/-	Rs. 425/-
Swing Motor	Rs. 750/-	Rs. 325/-
Flapper	Rs. 1250/-	Rs. 325/-
Capacitor 35-60 mfd	Rs. 899/-	Rs. 425/-
Replace Sensor	Rs. 799/-	Rs. 425/-
Non-Inverter Pcb Replace (New)	Rs. 4500/-	Rs. 425/-
Non-Inverter Pcb Repair	Rs. 1650/-	Rs. 425/-
Capacitor 10-25 Mfd	Rs. 599/-	Rs. 425/-
Inverter Pcb Replaced (IDU)	Rs.	Rs. 425/-

Parts

Description	Parts	Labour
Inverter PCB Replaced (ODU)	Rs.	Rs. 425/-
Replace LVT	Rs. 1300/-	Rs. 425/-
Capacitor 2-5 mfd	Rs. 375/-	Rs. 325/-
Relay Contactor	Rs. 1650/-	Rs. 325/-
Relay Contactor Mitsh/O. G	Rs. 2200/-	Rs. 325/-
Remote	Rs. 800/-	Rs. 250/-
ODU Fan Blade	Rs. 825/-	Rs. 425/-
Front Grill Cover	Rs.	Rs. 325/-
Compressor Grommet Set	Rs. 350/-	Rs. 425/-
Adjust Compressor Screw/Noise	Rs. 325/-	Rs. 425/-
Window/Split Fan Rubber	Rs. 400/-	Rs. 425/-
Window AC Fan Motor Repair	Rs. 1800/-	Rs. 425/-
Insulation Foam (per ft)	Rs. 35/-	Rs. 425
Rubber Insulation Foam (per ft)	Rs. 60/-	Rs. 425